


How to install necessary plug for VDR software on PC

1. Where is the plug software?

In the folder of "install necessary".

The direction is "CD\2 Software\install necessary".

It is in the CD or USB disk of DAU.



2. Install all the plug software in the folder of "install necessary" if possible.

If some plugs fail to install. That means the Windows system does not fit they. It does not matter.

